

Water Quality Analysis and Environmental Impact Studies on Varthur Lake

^[1] L.Munikrishna ^[2] Edwin A, ^[3] Deepa K POL, ^[4] Pallavi B C
^{[1][2][3][4]} Vemana Institute of Technology

Abstract: The study was conducted to assess the surface and ground water quality values of varthur lake which is a major tank in south taluk. Samples were collected in clean and sterilized plastic bottles of 2 litre capacity. The samples were collected to examine the water quality in the month of February 2018 of Varthur lake and brought to the laboratory for physico-chemical parameters analysis. Selected Parameters were analysed by standard methods of CENTRAL POLLUTION CONTROL BOARD OF INDIA. The surface and ground water quality of Varthur Lake has exaggerated due by the consequent changes and urbanization which indicated the physico-chemical concentrations of lakes found in high levels.

I. INTRODUCTION

Water is a prime natural resources, A basic human need and a precious national asset. Planning, Development and management of water resources need to be governed by national perspectives. All life depends on water and exists in nature in many forms like an ocean, river, lake, clouds, rain, snow and fog etc. However, strictly speaking chemically pure water does not exist for any appreciable length of time in nature. A lake is a large body of water surrounded by land, inhabited by various aquatic life forms for all practical purpose, pure water is considered to that which has low dissolved or suspended solids and obnoxious gases as well low in biological life. Such high quality of water may be required only for drinking purposes while for other uses like agriculture and industry, the quality of water can be quite flexible and water polluted up to a certain extent in a general sense can be regarded as pure. The lakes are also subjected to various natural processes taking place in the environment like the hydrologic cycle, with unprecedented developmental activities; human beings are responsible for choking several lakes to death. Storm water runoff and discharge of sewage into the lakes are a few of the common causes where various nutrients enter the aquatic ecosystems resulting in their death. Of all the water quality issues facing lakes everywhere, Eutrophication is of great concern. Eutrophication is a term used to describe the aging of a lake, resulting due to the accumulation of nutrients, sediments, silt and organic matter in the lake from the surrounding watershed (sulekhct al., 2012). The pace of urbanization is increasing globally, putting more pressure on local water quality. In addition to discharges untreated sewage of urban and industrial wastewater, urban areas add to poor water quality in number ways. The high concentration of impervious surfaces increases runoff from roads and can carry numerous pollutants such

as oils, heavy metals, rubber, and other automobile pollution into waterways and streams. The reduction in water percolation into the ground can also affect the quantity and quality of groundwater, and storm water runoff can overwhelm wastewater treatment systems when high volume flows exceed treatment capacities. India is facing a serious problem of natural resource scarcity, especially that of water in view of population growth and economic development. Most of fresh water bodies all over the world are getting polluted, thus decreasing the potability of water. Bangalore city does not have any perennial river. It is dependent on river cauvery which is about 140km away to provide water to its residents pumping water is an expensive business as the the population of Bangalore increases the demand for water to increase.

Sample collection

Samples were collected in clean and sterilized plastic bottles of 2 litre capacity. The samples were collected to examine the water quality in the month of February 2018 of Varthur lake and brought to the laboratory for physico-chemical parameters analysis. Selected Parameters were analysed by standard methods of CENTRAL POLLUTION CONTROL BOARD OF INDIA. The surface and ground water quality of Varthur Lake has exaggerated due by the consequent changes and urbanization which indicated the physico-chemical concentrations of lakes found in high levels. Despite of some conservation efforts made by the authorities this lake is threatening immeasurably. Continuous monitoring of lakes should be enacted properly as from the origin point at the end to overcome these situations.

II. MATERIALS AND METHODS

Study area : varthur lake is one of the largest lake located in bangalore south It has a large surface area and is the

main irrigation source to the nearby agricultural fields this lake has played an important role in maintaining water resources for irrigation since its construction over the centuries. The lake is surrounded by small farms that grow rice, ragi, coconut and flowers and variety of fruits and vegetables. The total land irrigated by the lake water amounts to 625 hec. The largest town in the immediate area in the varthur, which had a population of 5431 as per 1981 census. Varthur lake which has an area of 180.40 hec (445.8 acres) is the most largest lake in the Bangalore city.

PYSICO CHEMICAL ANALYSIS

Table 1: Result of physico- chemical analysis of ground water

PARAMETERS	WHO STANDARD	GROUND WATER SAMPLE				
		SAMPLE(1)	SAMPLE(2)	SAMPLE(3)	SAMPLE(4)	SAMPLE(5)
COLOUR	-	-	-	-	-	-
TDS (mg/l)	500	1160	1241	1570	1300	1612
pH	5.5-9.0	7.49	7.36	7.32	7.42	7.14
CONDUCTIVITY (uS/cm)	600	1818	1955	2460	2054	2550
TOTAL HARDNESS (mg/l of CaCO ₃)	500	460	236	540	568	532
CALCIUM(mg/l)	200	141.08	75.35	107.41	72.144	134.66
MAGNESIUM(mg/l)	100	26.24	11.664	66.09	94.28	47.628
CHLORIDES(mg/l)	250	310	302	352	200	320
SULPHATE(mg/l)	200	22	28	32	24	22
NITRATES(mg/l)	10	105	98	58	110	125
FLORIDES(mg/l)	0.6-1.2	1.8	1.5	1.2	1.9	2.2
IRON(mg/l)	1	0.32	0.8	1.2	1.5	0.56
COD(mg/l)	250	58	68	72	70	24
DISSOLED OXYGEN(mg/l)	4	4.11	4.82	4.12	3.11	2.10
SODIUM(Mg/l)	-	22	28	32	24	20
POTASSIUM(mg/l)	-	2	1	3	4	2
ALKALINITY(mg/l)	200	494	494	404	436	372

HEAVY METALS

CHROMIUM (ug/l)	0.05	1.946	89.03	00	50.03	0
ZINC(ug/l)	5	0.0	00	00	206.6	0
COPPER(ug/l)	1.5	0.02	0.05	0.04	0.00	0.01

Table 2: Results of physico-chemical analysis of surface

SURFACE WATER SAMPLE	WHO standards
TURBIDITY(NTU)	158
pH	7.52
CONDUCTIVITY(uS/cm)	2000
TOTAL DISSOLVED SOLIDS (mg/l)	1270
ALKALINITY(mg/l)	508
TOTAL HARDNESS	308
CALCIUM(mg/l)	8.93
MAGNESIUM(mg/l)	53.05
CHORIDE(mg/l)	350
SULPHATE(mg/l)	22
NITRATE(mg/l)	52
FLOURIDE(mg/l)	1.8
IRON(mg/l)	0.2
BOD(mg/l)	120
COD(mg/l)	180
SODIUM(mg/l)	45
POTASSIUM(mg/l)	4
HEAVY METALS	
CHROMIUM(ug/l)	00
ZINC(ug/l)	00
COPPER(ug/l)	0.15
LEAD(ug/l)	0.00
CADMIUM(ug/l)	0.05
MERCURY(ug/l)	-
ARSENIC(ug/l)	0.0
NICKEL(ug/l)	0.254

III. CONCLUSION

Water quality studies can bring sharp focus about the definite changes in different chemical constituents this include details of the result obtained from the analyses of 5 bore wells and 1 sewage samples from varthur lake surface sample high concentration of Chloride, Fluoride, Nitrate, Alkalinity and Total dissolved solids above permissible limit the surrounding varthur lake alkali concentration is high because of untreated industrial effluents and sewage water leaving into stream is the only reason for the increase of alkalies in ground water of the study area.

REFERENCES

- [1] "Assessment of physio- chemical parameters of varthur lake" Dr Ramkrishnaiah C R Associate professor. Department of civil engineering, BMS college of Engineering
- [2] "Ramachandra T V ,Ahalya N and Mandy payme ,status of varthur lake; opportunities for Restoration and sustainable management.
- [3] "Ramachandra T.V Spatial Analysis and characterization of lentic Ecosystem; A case Study of varthur Lake,Bangalore.
- [4] "Durga Madhab Mahapatra,H.N.Chanakya, varthur lake past,present and Future.
- [5] "Water and Wastewater Analysis-Central Pollution Control Board (Govt of India)